

 <b>National Transportation Safety Board</b> <b>FOREIGN NOTIFICATION</b> <b>AVIATION</b>		NTSB ID: CEN11RA295		Most Critical Injury: None	
		Occurrence Date: 03/14/2011		Investigated By: Foreign	
		Occurrence Type: Accident			
Location/Time					
Nearest City/Place Saanen		State	Zip Code	Local Time 1205	Time Zone UTC
Aircraft Information					
Registration Number N177EA		Aircraft Manufacturer ECLIPSE AVIATION CORP		Model/Series Number EA500	
Type of Aircraft: Airplane			Amateur Built Aircraft? No		
Injury Summary:	Fatal	Serious	Minor	None	5
Revenue Sightseeing Flight:			Air Medical Transport Flight:		
Narrative					
<p>Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:</p> <p>*** Note: The foreign authority was the source of this information. ***</p> <p>On March 14, 2011, at 1205 UTC, an Eclipse Aircraft Corporation, EA500, U.S. Registration N177EA, collided with a parked vehicle during landing at Saanen Aerodrome, Bern, Switzerland. The pilot and four passengers were not injured. The airplane was substantially damaged. The airplane was owned and operated by Liebherr-Geschäftsreiseflugzeug, GbR. Visual meteorological conditions prevailed for the flight. The flight originated from Innsbruck, Austria.</p> <p>This investigation is under the jurisdiction and control of the Swiss government. Any further information may be obtained from:</p> <p>Buro fur Flugunfalluntersuchungen, BFU          Bureau d'enquete sur les accidents d'aviation BEAA          Aircraft Accident Investigation Bureau, AAIB          Aeropole 1          Route de Morens          CH-1530 Payerne          Switzerland</p> <p>This report is for informational purposes only and contains only information released by, or obtained from, the AAIB of Switzerland.          Updated on Jun 6 2011 4:17PM</p>					
FOREIGN INFORMATION - SUBJECT TO CHANGG					